

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8





FIG.9



Title: HEATER COIL FOR GAS SENSOR,  
DETECTION ELEMENT FOR GAS SENSOR,  
CONTACT COMBUSTION TYPE GAS SENSOR,  
AND METHOD FOR MANUFACTURING  
CONTACT COMBUSTION TYPE GAS SENSOR

Inventor(s): Ikuo TAKAHASHI et al.

DOCKET NO.: 062800-0122

FIG.10




FIG.11




FIG.12




FIG.13




FIG. 14




FIG.15




FIG.16




FIG.17




FIG.18





FIG.19



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☒ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☒ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**